



Automation dimensions

	Min	Max
DW	900	4500
DH	1000	4600

Key
 LT = Automation full width
 HT = Automation full height
 CL = Cable length
 DW = Horizontal opening
 DH = Vertical opening

When taking measurements, consider:
 ** = 50 mm
 * = 250 mm
 (only for motor replacing)

DH	CL = Cable Length
≤ 3500	4000
> 3500	6000